Inspection Report for Flood Damage Work

1						
1	1	J.	T٤	2	•	_

1 Name of PIUs: - Cryan Viblanar

2 Name of Block/Road :-

Lah Sunka to sani chora Asthan talk

(A) For Road:

- 1. Damage Location/Chainage:- ch 850, 1050, 13 GO, 1475, 1645, 1750 m2 many
- 2. Damage Length

:- 246.00h

- 3. Nature of Damage
- 4. Details of Restoration Works :-
- Material being used in Restoration works:- Brich Sas (i)
- Equipment's/Tools being used in Restoration works:- Tractor (ii)
- Procedure taken up in Restoration works: (iii)
- (iv) Restored Length

:- 246.00m

\checkmark (B) For Bridge:

- 1. Damage Location/Chainage
- 2. Damage Length
- 3. Nature of Damage
- 4. Details of Restoration Works:
- (i) Material being used in Restoration works:-
- (ii) Equipment's/Tools being used in Restoration works:-
- (iii) Procedure taken up in Restoration works:-
- (iv) Restored Length

Signature of JE/AE/EE

(Name of Inspection) Executive Engineer R.W.D. Works Division Muzaffarpur East-1

GENERAL ABSTRACT

Name of Road

Lahsurka to Sanichra Asthan Tak

District

Muzaffarpur

Block

Minapur

Division

Muzaffarpur East-2

Length of Road (in Km)

2.175 Km

SI. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Jhama metal	10.189
2	Sand Filling	
3	Sand bag	0.000
4	H.P.	0.000
	GRAND SUB TOTAL	10.189
TOTAL C	COST OF PROJECT IN LACS =	10.189

3.01.2021 Major

ΑE

JΕ RWD

RWD

Technically approved for RS 10.19 lac.

(Rupeel Ten lac Mineteen thousand only)

RWD wone corele myzastamus