

## Inspection Report for Flood Damage Work

Date:-

1 Name of PIUs :- Gyan Vihhar

2 Name of Block/Road :- Repair of road from Nandana to Dharbhar

### (A) For Road:

1. Damage Location/Chainage :- ch-70, 105, 605, 717, 1077, 1228, 1375, 1504, 1618
2. Damage Length :- 1950 to 2380, 2635, 2875, 2970 with many places
3. Nature of Damage :- 1016.00m
4. Details of Restoration Works :-
  - (i) Material being used in Restoration works:- Bricks & S&S
  - (ii) Equipment's/Tools being used in Restoration works:- Tractor
  - (iii) Procedure taken up in Restoration works:-
  - (iv) Restored Length :- 1016.00m

### (B) For Bridge:

1. Damage Location/Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works :-
  - (i) Material being used in Restoration works:-
  - (ii) Equipment's/Tools being used in Restoration works:-
  - (iii) Procedure taken up in Restoration works:-
  - (iv) Restored Length :-

Signature of JE/AE/EE

  
Signature

(Name of Inspection)  
Executive Engineer  
R.W.D. Works Division  
Muzaffarpur East-1

## GENERAL ABSTRACT

Name of Road Repair of Road from Nandana to Dharpur

District Muzaffarpur

Block Minapur


Division Muzaffarpur East-2


Length of Road (in Km) 3.000 Km

Sl. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Jhama metal	28.851
2	Sand Filling	0.000
3	Sand bag	0.000
4	H.P.	0.000
	GRAND SUB TOTAL	28.851
TOTAL COST OF PROJECT IN LACS =		28.851


By 28.851

  
07.01.2021  
JE  
RWD

  
07/01/21  
AE  
RWD

  
07/01/21  
EE  
RWD

Technically approved for Rs. 28.85 lac. (Rupees twenty eight lac eighty five thousand only)

  
16.1.21  
S.E.  
R.W.D. Muzaffarpur