## Inspection Report for Flood Damage Work

Date:-

I Name of PlUs: Cryon Vistana

2 Name of Block/Road :-

Roma Rai Re ghar to Stankar Sich

## (A) For Road:

- 1. Damage Location/Chainage :- 48 to 80 m
- 32.00 2. Damage Length
- 3. Nature of Damage
- 4. Details of Restoration Works :-
- Material being used in Restoration works: Brien bat, Hum bifa (i)
- Equipment's/Tools being used in Restoration works:-(ii)
- Procedure taken up in Restoration works: (iii)
- :- 32.000 Restored Length (iv)

## (B) For Bridge:

- Damage Location/Chainage
- 2. Damage Length
- 3. Nature of Damage
- 4. Details of Restoration Works :-
- (i) Material being used in Restoration works:-
- (ii) Equipment's/Tools being used in Restoration works:-
- (iii) Procedure taken up in Restoration works:-
- (iv) Restored Length

Signature of JE/AE/EE

(Name of Inspection) Executive Engineer R.W.D. Works Division Muzaffarpur East-1

Sey 6.98 lac	.g Res		
-	0.803	TOTAL COST OF PROJECT IN LACS =	TOTAL CC
	6.905	GRAND SUB TOTAL	
	0.005	H.P.	4
	0.347	Sand bag	ω
	0.000	Sand Filling	2
	0.730	Jhama metal	_
	AMOUNI (LAKHS)	DESCRIPTION	SI. No.
	Xm	Length of Road (in Km) 0.300 Km	Length of R
		Muzaffarpur East-2	Division
		Minapur	Block
		Muzaffarpur	District
		toad Rama Rai Ke Ghar to Shankar Sah	Name of Road
		GENERAL ABSTRACT	

RWD

Technically approved for RS 6.98 Lac

Rus word ctrcle muzadfaznu

K. 1.31