Inspection Report for Flood Damage Work

Date:-1 Name of PIUs: - Oyan Vibhaner 2 Name of Block/Road: Once Salery Cocal to Budde mila (A) For Road: 1. Damage Location/Chainage 26 to of 102 Damage Length :- 102.752 Nature of Damage 4. Details of Restoration Works :-Material being used in Restoration works:- Brain 5 45 (I) Equipment's/Tools being used in Restoration works:- Tractor, JCB. (Π) Procedure taken up in Restoration works: (iv) Restored Length :- 102.75 ~ (B) For Bridge: 1. Damage Location/Chainage :-Damage Length 3. Nature of Damage 4. Details of Restoration Works :-(i) Material being used in Restoration works:-(ii) Equipment's/Tools being used in Restoration works:-(iii) Procedure taken up in Restoration works:-(iv) Restored Length

Signature of JE/AE/EE

Signature

(Name of Inspection)

Executive Engineer

R.W.D. Works Division

Muzaffarpur East-1

GENERAL ABSTRACT

Name of Road

Brick Soling Road to Budhu Mia

District

Muzaffarpur

Block

Minapur

Division

Muzaffarpur East-2

Length of Road (in Km)

0.400 Km

Longitude		AMOUNT (LAKHS)
SI. No.	DESCRIPTION	7.004
1	Jhama metal	0.000
2	Sand Filling	0.000
3	Sand bag	0.000
4	H.P.	7.004
	GRAND SUB TOTAL	7.004
TOTAL (COST OF PROJECT IN LACS =	

say 7-00 lac

57.01.2021 Mayor

ΑE

JE RWD

RWD

RWD

Technically approved for R8 7-00 lac (Rupeel seven lacenly)

> Run wone crecke muzaffarpur