Inspection Report for Flood Damage Work

Date:-

1 Name of PIUs: - byan viblang

2 Name of Block/Road: - Minafur/ NIH-77 Dharampur Panchayat Bhawan to prostate yeder tole Ram Das Rai Loure Tan.

- 1. Damage Location/Chainage :- ch-132, 170, 308, 480 m.
- 2. Damage Length
- :- 86.60m
- 3. Nature of Damage
- 4. Details of Restoration Works :-
- Material being used in Restoration works:- Brich bets (i)
- Equipment's/Tools being used in Restoration works:- Trace tor (ii)

:-

- Procedure taken up in Restoration works: (iii)
- Restored Length (iv)
- :- 86.60m

(B) For Bridge:

- 1. Damage Location/Chainage
- 2. Damage Length
- 3. Nature of Damage
- 4. Details of Restoration Works:
- (i) Material being used in Restoration works:-
- (ii) Equipment's/Tools being used in Restoration works:-
- (iii) Procedure taken up in Restoration works:-
- (iv) Restored Length

Signature of JE/AE/EE

(Name of Inspection)

Executive Engineer R.W.D. Works Division Muzaffarpur East-}

GENERAL ABSTRACT

Name of Road

NH-77 Dharampur Phanchayat Bhawan to Mothaha Yadav Tola Ram Das Rai House Tak

District

Muzaffarpur

Block

Minapur

Division

Muzaffarpur East-2

Length of Road (in Km)

DESCRIPTION	
hama metal	AMOUNT (LAKHS)
Sand Filling	7.740
Sand bag	0.000
I.P.	0.000
RAND SUB TOTAL	0.000
T OF PROJECT IN LACS =	7.740
	7.740
	and Filling and bag I.P. RAND SUB TOTAL

JΕ

RWD

ΑE

RWD

RWD

Technically approved for Rs 7.74 lacs, (Rupus Sum lacs Sumty four Hourand) ons,

RWD, Work einel

muzaffanja