

Inspection Report for Flood Damage Work

Date:-

1 Name of PIUs :- Gyan Vihar

2 Name of Block/Road :- 2084 To 8 to Hazratpur

(A) For Road:

- ✓ 1. Damage Location/Chainage :- 4-203, 360, 450, 750, 825, 1000, 1080, 1164,
2. Damage Length :- 1205, 1410, 1560
3. Nature of Damage :- 302.05m
4. Details of Restoration Works :-
(i) Material being used in Restoration works:- ~~Trecker~~ Brientalis
(ii) Equipment's/Tools being used in Restoration works:- Trecker, JCB.
(iii) Procedure taken up in Restoration works:
(iv) Restored Length :- 302.05m

(B) For Bridge:

1. Damage Location/Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works :-
(i) Material being used in Restoration works:-
(ii) Equipment's/Tools being used in Restoration works:-
(iii) Procedure taken up in Restoration works:-
(iv) Restored Length :-

Signature of JE/AE/EE


Signature


~~Executive Engineer~~
R.W.D. Works Division
Muzaffarpur East-1

GENERAL ABSTRACT


Name of Road L084 T08 to Hazratpur (VR63)
District Muzaffarpur
Block Minapur
Division Muzaffarpur East-2
Length of Road (in Km) 2.413 Km

Sl. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Jhama metal	9.952
2	Sand Filling	0.000
3	Sand bag	0.000
4	H.P.	0.000
	GRAND SUB TOTAL	9.952
TOTAL COST OF PROJECT IN LACS =		9.952


sy 9.95 lac


07.01.2021


JE
RWD



AE
RWD


RWD

Technically approved for Rs. 9.95 lac (Rupees
nine lac Ninety five thousand only)


S.E.
R.W.D. Wookcircle
Muzaffarpur