Inspection Report for Flood Damage Work

Date:-	
1 Name of PlUs:-	Shakor
2 Name of Block/Road :-	Dharohi Patti pur Rd to Da rahia Path
(A) For Road:	
Damage Location/Chainage	:-ch-1100, 1170, 125, 1260, 1840, 2620 and many place
2 D	:- 203.30-
3. Nature of Damage	:-
4. Details of Restoration Works	; -
(i) Material being used in Res	storation works: - Brien Sal

Equipment's/Tools being used in Restoration works:- Tree tor

: 203.30-

(B) For Bridge:

(ii)

(iii)

(iv)

Damage Location/Chainage : Damage Length :-

Restored Length

- 3. Nature of Damage :-
- 4. Details of Restoration Works:
- (i) Material being used in Restoration works:-
- (ii) Equipment's/Tools being used in Restoration works:-

Procedure taken up in Restoration works:

- (iii) Procedure taken up in Restoration works:-
- (iv) Restored Length :

Signature of JE/AE/EE

Signature

(Name of Inspection)

Executive Engineer

R.W.D. Works Division

Muzaffarpur East-1

GENERAL ABSTRACT

Name of Road

Dharahi Patti PWD RD to Darahia Path

District

Muzaffarpur

Block

Minapur

Division

Muzaffarpur East-2

Length of Road (in Km)

0.000 Km

SI. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Jhama metal	8.959
	Sand Filling	0.000
	Sand bag	0.000
	H.P.	0.000
	GRAND SUB TOTAL	8.959
	COST OF PROJECT IN LACS =	8.959

Say 8.960 Lac

JE

RWD

ΑE

RWD

of a my

RWD

Technically approved for RS 8.96 lac.
(Rupees sight lac ninety six thousand only)

RWD WORK CITCLE
musaffasput