

Inspection Report for Flood Damage Work

Date:-

1 Name of PIUs :- Gyan vibhakar

2 Name of Block/Road :- Aurai / Gangoli mahopur road to madhuban Besi

(A) For Road:

1. Damage Location/Chainage :- 0.800 km, 0.900 km, 1.00 km
2. Damage Length :- 0.06705 Km
3. Nature of Damage :-
4. Details of Restoration Works :-
 - (i) Material being used in Restoration works:- Brick bats
 - (ii) Equipment's/Tools being used in Restoration works:- Tractors
 - (iii) Procedure taken up in Restoration works:
 - (iv) Restored Length :- 0.06705 Km

(B) For Bridge:

1. Damage Location/Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works :-
 - (i) Material being used in Restoration works:-
 - (ii) Equipment's/Tools being used in Restoration works:-
 - (iii) Procedure taken up in Restoration works:-
 - (iv) Restored Length :-

Signature of JE/AE/EE


Signature

(Name of Inspection)

कार्यपालक अभियंता

ग्रामीण कार्य विभाग

कार्य प्रमंडल, मुजफ्फरपुर पूर्वी-1

GENERAL ABSTRACT

Name of Road : Gangoli Madhopur Road to Madhuban Besi

District : Muzaffarpur

Block : Aurai

Division : Muzaffarpur East-2

Length of Road (in Km)

1.174 Km

Sl. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Earthwork	0.000
2	Jhama metal	9.734
3	Sand Filling	0.000
4	Sand bag	0.000
5	H.P.	0.000
	GRAND SUB TOTAL	9.734
TOTAL COST OF PROJECT IN LACS =		9.734

SEC
11/11/21

JE
RWD

AE
11/11/21
AE
RWD

EE
11/11/21
EE
RWD

Technically approved for Rs 9.734 lac
(Rupees nine lac seventy three thousand
four hundred only)

11/11/21
अधीक्षण अभियंता
ग्रामीण कार्य विभाग
कार्य अंचल, मुजफ्फरपुर