# Inspection Report for Flood Damage Work

#### Date:-

1 Name of PIUs: - Gyan Vibhakar

2 Name of Block/Road: - Aurai / Najagaon to Ganguli mashopur road.

## (A) For Road:

- 1. Damage Location/Chainage :- 1.00 km
- 2. Damage Length :- 0.07468 Km
- 3. Nature of Damage
- 4. Details of Restoration Works:
- Material being used in Restoration works:- Brick bots (i)
- Equipment's/Tools being used in Restoration works:- Tractor; (ii)
- Procedure taken up in Restoration works: (iii)
- (iv) Restored Length :- 0.07468 Km

### (B) For Bridge:

- 1. Damage Location/Chainage
- 2. Damage Length
- 3. Nature of Damage
- 4. Details of Restoration Works:
- Material being used in Restoration works:-
- (ii) Equipment's/Tools being used in Restoration works:-
- (iii) Procedure taken up in Restoration works:-
- (iv) Restored Length

Signature of JE/AE/EE

(Name of Inspection)

कार्यपालक अभियंता ग्रामीण कार्य विभाग कार्य प्रमंडल, मुज५फरपुर पूर्वी-1

## **GENERAL ABSTRACT**

Name of Road

Nayagaon to Ganguli Madhopur Road

District

Muzaffarpur

Block

Aurai

Muzaffarpur East-2

Division

7.700 Km

| Road (in Km)             | AMOUNT (LAKHS) |
|--------------------------|----------------|
| DESCRIPTION              | 0.000          |
| Earthwork                | 7.866          |
| Jhama metal              | 0.000          |
| Sand Filling             | 0.000          |
| Sand bag                 | 0.000          |
| H.P.                     | 7.866          |
| GRAND SUB TOTAL          | 7.866          |
| OST OF PROJECT IN LACS = |                |

54

JΕ

**RWD** 

Technically approved for RS 7-866 lace
(Rupees seven lac signify six thousand six hundred only)

अधीक्षण अभियंता ग्रामीण कार्य विभाग कार्य अंचल,मुजफ्फरपुर