Inspection Report for Flood Damage Work

Equipment's/Tools being used in Restoration works:- Tractor.

:- 0.05335 Km

Date:-	보다 하는 것이 되지 않는데 보다는 것이 하지만 하는데 하는데 하셨다.
1 Name of PIUs: - Cryan with	akar
2 Name of Block/Road :- Awai	1 Loza- Pmasy road Loy6 to Chakki Rander
(A) For Road.	le frantak.
1. Damage Location/Chainage	:- 0.201m, 0.3001m, 0. Avolon
2. Damage Length	:- 0.05335 Km
3. Nature of Damage	
4. Details of Restoration Works	그리지 하는 경기가 있는 것 같아. 이번 사람들은 사람들이 살아가 되었다.
(i) Material being used in Res	storation works: Drick bats

(iv) Restored Length(B) For Bridge:

(ii) (iii)

- 1. Damage Location/Chainage :-
- Damage Length
 Nature of Damage
- 4. Details of Restoration Works:-
- (i) Material being used in Restoration works:-
- (ii) Equipment's/Tools being used in Restoration works:-

Procedure taken up in Restoration works:

- (iii) Procedure taken up in Restoration works:-
- (iv) Restored Length

Signature of JE/AE/EE

Signature

(Name of Inspection) कार्यपालक अभियंता प्रामीण कार्य विभाग कार्य प्रमंडल,मुजफ्फरपुर पूर्वी-1

GENERAL ABSTRACT

Name of Road

L026 - PMGSY Road L046 to Chakki Ramdev Ke Ghar Tak

District

Muzaffarpur

Block

Aurai

Division

Muzaffarpur East-2

Length of Road (in Km)

0.800 Km

SI. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Jhama metal	0.883
2	Sand Filling	0.000
3	Sand bag	0.000
4	H.P.	0.000
	GRAND SUB TOTAL	0.883
TOTAL C	OST OF PROJECT IN LACS =	0.883

1111)21

RWD

ASITOIM

RWD

EE TI

Technically approved for RSO-583 lac (Rupees Eighty Bight thousand three hundred only)

> अधीक्षण अभियंता ग्रामीण कार्य विभाग कार्य अंचल,मुजफ्फरपुर