Inspection Report for Flood Damage Work

Date:-
1 Name of PIUs:- ayan vibhakar 1 Name of PIUs:- ayan vibhakar
2 Name of Block/Road: (A) For Road: 1. Damage Location/Chainage 2. Damage Length 3. Nature of Damage 4. Details of Restoration Works: - Or 3 to 1m, or 950 lan,
(11) Equipment 5/10015 being used in resolution
(iii) Procedure taken up in Restoration works.
(iv) Restored Length :- 0-17522 Km
(B) For Bridge:
 Damage Location/Chainage :- Damage Length :- Nature of Damage :- Details of Restoration Works :- Material being used in Restoration works:- Equipment's/Tools being used in Restoration works:- Procedure taken up in Restoration works:-
(iv) Restored Length :-

Signature of JE/AE/EE

(Name of Inspection) कार्यपालक अभियंता ग्रामीण कार्य विभाग कार्य प्रमंडल,मुजफ्करपुर पूर्वी-1

GENERAL ABSTRACT

Name of Road

L030 -L029 to Misraulia

District

Muzaffarpur

Block

Aurai

Division

Muzaffarpur East-2

Length of Road (in Km)

2.353 Km

	Road (In NIII)	AMOUNT (LAKHS)
SI. No.	DESCRIPTION	2.270
1	Jhama metal	0.000
2	Sand Filling	0.000
3	Sand bag	0.000
4	H.P.	2.270
1	GRAND SUB TOTAL	2.270
TOTAL C	OST OF PROJECT IN LACS =	

11/1/21

JE

RWD

ASMOIM

AE

RWD

Pan EE 1977

Technically approved for RS 2-27 lac (Rybers two lac twenty seven thousand only)

> अधीक्षण अभियंता ग्रामीण कार्य विभाग कार्य अंचल,मुजफ्फरपुर