

## Inspection Report for Flood Damage Work

Date:-

1 Name of PIUs :- Gyan Vibhakar

2 Name of Block/Road :- Aurai / L-56 NH-77 Katanjha Tolo to Kalyanpur (VR-32)

### (A) For Road:

1. Damage Location/Chainage :- 0.5177 km, 0.7201 km, 0.830 m
2. Damage Length :- 0.11614 Km
3. Nature of Damage :-
4. Details of Restoration Works :-
  - (i) Material being used in Restoration works:- Brick bats
  - (ii) Equipment's/Tools being used in Restoration works:- Tractor
  - (iii) Procedure taken up in Restoration works:-
  - (iv) Restored Length :- 0.11614 Km

### (B) For Bridge:

1. Damage Location/Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works :-
  - (i) Material being used in Restoration works:-
  - (ii) Equipment's/Tools being used in Restoration works:-
  - (iii) Procedure taken up in Restoration works:-
  - (iv) Restored Length :-

Signature of JE/AE/EE

  
Signature

(Name of Inspection)  
कार्यपालक अभियंता  
ग्रामीण कार्य विभाग  
कार्य प्रमंडल, मुजफ्फरपुर पूर्वी-1



### GENERAL ABSTRACT

Name of Road L056 NH-77 Kataujha T010 to Kalyanpur (VR32)

District Muzaffarpur

Block Aurai

Division Muzaffarpur East-2

Length of Road (in Km)

3.715 Km

Sl. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Earthwork	
2	Jhama metal	0.000
3	Sand Filling	5.838
4	Sand bag	0.000
5	H.P.	0.000
	GRAND SUB TOTAL	0.000
		5.838
TOTAL COST OF PROJECT IN LACS =		5.838

54  
11/11/21

JE  
RWD

11/11/21  
AE  
RWD

11/11/21  
EE  
RWD

Technically approved for Rs 5.838 lac  
(Rupees five lac Eighty three thousand eight  
hundred only)

अधीक्षण अभियंता  
ग्रामीण कार्य विभाग  
कार्य अंचल, मुजफ्फरपुर