

Inspection Report for Flood Damage Work

Date:-

1 Name of PIUs :- Gyan Vibhakar

2 Name of Block/Road :- Aurai / L058 Chaugbara L056 to Dharharwa (VR33)


(A) For Road:

1. Damage Location/Chainage :- many places
2. Damage Length :- 0.03869 Km
3. Nature of Damage :-
4. Details of Restoration Works :-
 - (i) Material being used in Restoration works:- Brick bats
 - (ii) Equipment's/Tools being used in Restoration works:- Tractor.
 - (iii) Procedure taken up in Restoration works:-
 - (iv) Restored Length :- 0.03869 Km

(B) For Bridge:

1. Damage Location/Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works :-
 - (i) Material being used in Restoration works:-
 - (ii) Equipment's/Tools being used in Restoration works:-
 - (iii) Procedure taken up in Restoration works:-
 - (iv) Restored Length :-

Signature of JE/AE/EE


Signature

(Name of Inspection)

कार्यपालक अभियंता
ग्रामीण कार्य विभाग
कार्य प्रमंडल, मुजफ्फरपुर पूर्वी-1

GENERAL ABSTRACT

Name of Road L058 Chandbara L056 to Dharharwa (VR33)

District Muzaffarpur

Block Aurai

Division Muzaffarpur East-2

1.650 Km

Length of Road (in Km)		AMOUNT (LAKHS)
Sl. No.	DESCRIPTION	
1	Jhama metal	0.989
2	Sand Filling	0.000
3	Sand bag	0.000
4	H.P.	0.000
	GRAND SUB TOTAL	0.989
TOTAL COST OF PROJECT IN LACS =		

Seep
11/11/21
JE
RWD

11/11/21
AE
RWD

11/11/21
EE
RWD

Technically approved for Rs 0.989 lac
(Rupees ninety eight thousand nine hundred only)

11/11/21
अधीक्षण अभियंता
ग्रामीण कार्य विभाग
कार्य अंचल, मुजफ्फरपुर