

Inspection Report for Flood Damage Work

Date:-

1 Name of PIUs :- Gyan vibhakar

2 Name of Block/Road :- Aurai / Beriya to Sambhuta

(A) For Road:

1. Damage Location/Chainage :- 0.2015 to 0.5001 km, 0.7001 km
2. Damage Length :- 0.10907 Km
3. Nature of Damage :-
4. Details of Restoration Works :-
 - (i) Material being used in Restoration works:- Brick bats
 - (ii) Equipment's/Tools being used in Restoration works:- Tractor.
 - (iii) Procedure taken up in Restoration works:
 - (iv) Restored Length :- 0.10907 Km

(B) For Bridge:

1. Damage Location/Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works :-
 - (i) Material being used in Restoration works:-
 - (ii) Equipment's/Tools being used in Restoration works:-
 - (iii) Procedure taken up in Restoration works:-
 - (iv) Restored Length :-

Signature of JE/AE/EE


Signature

(Name of Inspection)

कार्यपालक अभियंता

ग्रामीण कार्य विभाग

कार्य प्रमंडल, मुजफ्फरपुर पूर्वी-1

GENERAL ABSTRACT

Name of Road Beriya to Sambhuta

District Muzaffarpur

Block Aurai

Division Muzaffarpur East-2

Length of Road (in Km) 2.338 Km

| Sl. No. | DESCRIPTION | AMOUNT (LAKHS) |
|---------------------------------|-----------------|----------------|
| 1 | Earthwork | 0.000 |
| 2 | Jhama metal | 5.000 |
| 3 | Sand Filling | 0.000 |
| 4 | Sand bag | 0.000 |
| 5 | H.P. | 0.000 |
| | GRAND SUB TOTAL | 5.000 |
| TOTAL COST OF PROJECT IN LACS = | | 5.000 |

Secy
11/1/21
JE
RWD

AD
11/1/21
AE
RWD

9 am
11/1/21
EE
RWD

*Technically approved for RS 5.00 lac
(Rupees five lac only)*

18-1-21
अधीक्षक अभियंता
ग्रामीण कार्य विभाग
कार्य अंचल, मुजफ्फरपुर