

Inspection Report for Flood Damage Work

Date:-

1 Name of PIUs :- *Ayan vibhakar*

2 Name of Block/Road :- *Aurai) Dam hiaday Shan house mabarsha to Benipur.*

(A) For Road:

1. Damage Location/Chainage :- *many places*
2. Damage Length :- *0.02896 Km*
3. Nature of Damage :-
4. Details of Restoration Works :-
 - (i) Material being used in Restoration works:- *Brick bats*
 - (ii) Equipment's/Tools being used in Restoration works:- *Tractor.*
 - (iii) Procedure taken up in Restoration works:
 - (iv) Restored Length :- *0.02896 Km*

(B) For Bridge:

1. Damage Location/Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works :-
 - (i) Material being used in Restoration works:-
 - (ii) Equipment's/Tools being used in Restoration works:-
 - (iii) Procedure taken up in Restoration works:-
 - (iv) Restored Length :-

Signature of JE/AE/EE

[Signature]
18.1.21
Signature

(Name of Inspection)

कार्यपालक अभियंता
ग्रामीण कार्य विभाग
कार्य प्रमंडल, मुजफ्फरपुर पूर्वी-1

GENERAL ABSTRACT

Name of Road Ram Hirday Snan House Madarsha to Benipur

District Muzaffarpur

Block Aurai

Division Muzaffarpur East-2

Length of Road (in Km) 1.270 Km

| Sl. No. | DESCRIPTION | AMOUNT (LAKHS) |
|---------------------------------|-----------------|----------------|
| 1 | Jhama metal | 2.293 |
| 2 | Sand Filling | 0.000 |
| 3 | Sand bag | 0.000 |
| 4 | H.P. | 0.000 |
| | GRAND SUB TOTAL | 2.293 |
| TOTAL COST OF PROJECT IN LACS = | | 2.293 |

scup
11/11/24
JE
RWD

AD 11/10/17
AE
RWD

scup
11/11/24
EE
RWD

Technically approved for Rs 2.293 lac
(Rupees two lac twenty nine thousand
three hundred only)

scup
11/11/24
अधीक्षण अभियंता
ग्रामीण कार्य विभाग
कार्य अंचल, मुजफ्फरपुर