Inspection Report for Flood Damage Work

Date:-		
1 Name of PIUs: - Ciyon vibhalan		
2 Name of Block/Road: - Awai / Dakbangla Chowk to Chaubhory (A) For Road: hue Harmi tola.		
(A) For Road: hue Harmi tola.		
1. Damage Location/Chainage :- 0.150 p. 200 km, 0.60 km		
2. Damage Length :- 0.04.145 Km		
3. Nature of Damage :-		
4. Details of Restoration Works:		
(i) Material being used in Restoration works:- Brick bots		
(ii) Equipment's/Tools being used in Restoration works:- Tractor.		
(iii) Procedure taken up in Restoration works:		

:- 0.04145 Km

(B) For Bridge:

(iv)

- 1. Damage Location/Chainage :-
- 2. Damage Length

Restored Length

- 3. Nature of Damage
- 4. Details of Restoration Works:
- (i) Material being used in Restoration works:-
- (ii) Equipment's/Tools being used in Restoration works:-
- (iii) Procedure taken up in Restoration works:-
- (iv) Restored Length

Signature of JE/AE/EE

Signature

tola Hote

(Name of Inspection) कार्यपालक अभियंता ग्रामीण कार्य विभाग कार्य प्रमंडल,मुजफ्फरपुर पूर्वी-1

GENERAL ABSTRACT

Name of Road

Dakbangala Chowk to Choudhary Tola Hote Hue Harmi Tola

District

Muzaffarpur

Block

Aurai

Division

Muzaffarpur East-2

Length of Road (in Km)

0.820 Km

SI. No.	DESCRIPTION	0.020 KIII
1	Earthwork	AMOUNT (LAKHS)
2	Jhama metal	0.000
3	Sand Filling	4.203
4	Sand bag	0.000
5	H.P.	0.000
	GRAND SUB TOTAL	0.000
		4.203
DTAL COST OF PROJECT IN LACS =		4,203

Secy 11)1/4

JE RWD JES JOIN

ΑE

RWD

EE TI

RWD

Technically approved for RS 4.203 lac (Rypees four lac thronty thousand three hundred only)

> अधीक्षण अभियंता ग्रामीण कार्य विभाग कार्य अंचल,मुजफ्फरपुर