Inspection Report for Flood Damage Work

Date:-1 Name of PIUs: - Cryan vibhalcar 2 Name of Block/Road: - Awrai / Loy7 Loy6 to Tora iwar (VR 24) (A) For Road: 1. Damage Location/Chainage :- many Places
2. Damage Length :- 0-07529 Km 3. Nature of Damage 4. Details of Restoration Works :-Material being used in Restoration works:- Brick both (i) Equipment's/Tools being used in Restoration works: (ii) Procedure taken up in Restoration works: (iii) (iv) Restored Length :- 0.07529 Km (B) For Bridge: 1. Damage Location/Chainage 2. Damage Length 3. Nature of Damage 4. Details of Restoration Works: Material being used in Restoration works:-(i) (ii) Equipment's/Tools being used in Restoration works:-(iii) Procedure taken up in Restoration works:-(iv) Restored Length

Signature of JE/AE/EE

Signature
(Name of Inspection)
कार्यपालक अभियंता
प्रामीण कार्य विभाग
कार्य प्रमंडल, मुजफ्फरपुर पूर्वी-1

GENERAL ABSTRACT

Name of Road

L047 L046 to Tarajiwar (VR24)

District

Muzaffarpur

Aurai

Block

Muzaffarpur East-2

Division Length of Road (in Km)

1.100 Km

SI. No.	DESCRIPTION	AMOUNT (LAKHS)
SI-NO.	Earthwork	0.000
$-\frac{1}{2}$	Jhama metal	3.824
$\frac{1}{3}$	Sand Filling	0.000
4	Sand bag	0.000
5	H.P.	0.000
	GRAND SUB TOTAL	3.824
TOTAL (COST OF PROJECT IN LACS =	3.824

sucy

RWD

AE NOINA

Technically approved for RS 3-824 Lac (Rupeel Three lac Eighty two thousand four hundred only)

अधीक्षण अभियंता ग्रामीण कार्य विभाग कार्य अंचल,मुजपफरपुर