

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD

Name of Scheme: Phenhara Main Road to Bara Parsaul		
Hazards	Flood/Rain	
Division: Pakridaya	District: East Champaran	Actual Length (in km): 2.399km
Damage Length (in km): 0.049 km	Damages Location/Chainage: 0.300 km, 0.350 km, 0.650 km	
Name of Scheme/Programme:	FD R(3054)	
Status of Project:	Under Agreement/Out of Agreement	
Sr. No.	Parameters to be Checked in Restoration work	Remarks : (S/U)
1.	Pavement (BT/CC) BT	S
a)	Condition of Surfacing	S

Description of observation :

MSS surfacing work is in good condition

b)	Adequate Thickness of pavement layers constructed	S
Description of observation : GSB Gr-II - 100mm WBM Gr III - 75mm MSS - 20mm		
c)	Quality of Construction Material Used	S

Description of observation :

Good quality material used.

d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.	N.A.
Description of observation : N.A.		
e)	Compaction of flanks/ slope & raincuts	

Description of observation :

Flank work in progress

2	Cross Drainage Structure	
a)	Condition of head walls in Hume pipe culverts	S
b)	Condition of Vent Clearance	S
c)	Condition of railings/Slab/approach for Bridges	N.A.

Description of observation of CD works :

found in good condition

Remark if any:

Flank work in progress

Overall Rating

Satisfactory (S) / Unsatisfactory (U)	S
---------------------------------------	----------

Name of Officer: **Ratnesh Paswan**

Designation: **E.E.**

[Signature]
01/07/21
E.E.

[Signature]
1.7.21
(Signature)
E.E.