

Black-Singhwar

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD

Name of Scheme: NH-57 SHASTRI CHOWK TO PWD PATH

Hazards Flood/Rain

Division: DARBHANGA-2 District: DARBHANGA Actual Length (in km): 0.850 km

Damage Length (in km): 0.640 km Damages Location/Chainage: 0 to 640 Meter

Name of Scheme/Programme:

Status of Project: Under Agreement/Out of Agreement

Sr. No.	Parameters to be Checked in Restoration work	Remarks : (S/U)
1.	Pavement (BT/CC) <u>CC</u>	
a)	Condition of Surfacing	<u>'S'</u>

Description of observation : CC surface found in good condition.

b)	Adequate Thickness of pavement layers constructed	<u>'S'</u>
Description of observation : <u>Adequate thickness found.</u>		

c)	Quality of Construction Material Used	<u>'S'</u>
Description of observation : <u>Good quality material used</u>		

d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.	<u>'S'</u>
Description of observation : <u>found in good condition.</u>		

e)	Compaction of flanks/ slope & raincuts	
Description of observation : <u>flank work not done, in progress.</u>		

2	Cross Drainage Structure	
a)	Condition of head walls in Hume pipe culverts	
b)	Condition of Vent Clearance	
C)	Condition of railings/Slab/approach for Bridges	

Description of observation of CD works : CD work not done, due to water logging

Remark if any:

Overall Rating

Satisfactory (S) / Unsatisfactory (U) 'S'

Name of Officer: CHANDRA SHEKHAR AZAD

Designation: E.E.

02/07/21
A.E.

02/07/21
(Signature)