

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD

Name of Scheme: *Bahadurganj PWD Road to Dingsal via Balubasti*

Hazards: *Flood/Rain*

Division: *Kishanganj-1* District: *Kishanganj* Actual Length (in km): *0.787*

Damage Length (in km): *0.050* Damages Location/Chamage: *100m*

Name of Scheme/Programme: *FD R*

Status of Project: *Under Agreement/Out of Agreement*

Sr. No. Parameters to be Checked in Restoration work Remarks: (S/U)

1. Pavement (BT/CC) *BT*

a) Condition of Surfacing *S*

Description of observation:

No defect

b) Adequate Thickness of pavement layers constructed *S*

Description of observation:

M.S.S. 20 mm thickness,

c) Quality of Construction Material Used *S*

Description of observation:

Good.

d) Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc *S*

Description of observation:

No Undulation

e) Compaction of flanks/ slope & raincuts *S*

Description of observation:

At few place, raincut bound, Roads Needs to be Maintained

2 Cross Drainage Structure

a) Condition of head walls in Hume pipe culverts

b) Condition of Vent Clearance

c) Condition of railings/Slab/approach for Bridges

Description of observation of CD works:

No provision in this Estimate

Remark if any:

Overall Rating

Satisfactory (S) / Unsatisfactory (U)

Satisfactory

Name of Officer: *Mahesh Prasad Gupta*

Designation: *EE, RWD, Regional Lab. Purnea*

CHN
02/07/2021
(Signature)