

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD

Name of Scheme: <u>Bhurna - Kalosohani Via Kadamola Kishanganj Bahadurpatti PWD Road</u>		
Hazard: <u>Flood/Rain</u>		
Division: <u>Kishanganj-I</u>	District: <u>Kishanganj</u>	Actual Length (in km): <u>2.700</u>
Damage Length (in km): <u>0.050 km</u>	Damages Location/Chainage: <u>1050, 1650 m.</u>	
Name of Scheme/Programme: <u>FDR</u>		
Status of Project: <u>Under Agreement/Out of Agreement</u>		
Sr. No.	Parameters to be Checked in Restoration work	Remarks : (S/U)
1.	Pavement (BT/CC)	<u>BT.</u>
a)	Condition of Surfacing	<u>S</u>
Description of observation : <u>Good.</u>		
b)	Adequate Thickness of pavement layers constructed	<u>S</u>
Description of observation : <u>M.S.S. 20mm thickness</u>		
c)	Quality of Construction Material Used	<u>S</u>
Description of observation : <u>Good.</u>		
d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.	<u>S</u>
Description of observation : <u>No Undulation</u>		
e)	Compaction of flanks/ slope & raincuts	
Description of observation : <u>At some places, raincut found, need to be repaired both side of flank damaged due to rain. need to be repaired</u>		
2	Cross Drainage Structure	
a)	Condition of head walls in Hume pipe culverts	
b)	Condition of Vent Clearance	
c)	Condition of railings/Slab approach for Bridges	
Description of observation of CD works : <u>No provision in the estimate</u>		
Remark if any:		

Overall Rating

Satisfactory (S) / Unsatisfactory (U)	<u>Satisfactory</u>
---------------------------------------	---------------------

Name of Officer: Mahesh Pd Gupta.

Designation: E.E., R.W.D. Regional Lab. Purnea

MAHESH
(Signature) 02/07/2021