

INSPECTION REPORT FOR FLOOD / RAIN DAMAGE ROAD

Name of Scheme:	KUMHRAULI PWD ROAD REO ROAD TO CHANUA TOL TAK.		
Hazards	Flood/Rain		
Division :	DARBHANGA-2	District: DARBHANGA	Actual Length (in km): 1.130 Km
Damage Length (in km):	0.450 Km.	Damages Location/Chainage:	150 to 400 Metre
Name of Scheme/Programme:			
Status of Project:	Under Agreement/On. of Agreement		
Sr. No.	Parameters to be Checked in Restoration work		Remarks : (S/U)
1.	Pavement (BT/CC)	CC	S'
a)	Condition of Surfacing		

Description of observation :

Condition of cc Pavement is good
out of 450 M only 250 M Constructed.

b)

Adequate Thickness of pavement layers constructed

S'

Description of observation :

Adequate thickness found

c)

Quality of Construction Material Used

S'

Description of observation :

Good quality of Material used.

d)

Whether free from any defects and Irregularity example-
Surface Cracks, Undulation, exposed aggregates in case of
CC Pavement, Poor workmanship, etc.

S'

Description of observation :

Found in good Condition

e)

Compaction of flanks/ slope & raincuts

Description of observation :

Flank work in progress.

2

Cross Drainage Structure

a)

Condition of head walls in Hume pipe culverts

NA

b)

Condition of Vent Clearance

NA

C)

Condition of railings/Slab/approach for Bridges

NA

Description of observation of CD works :

NA

Remark if any:

Overall Rating

Satisfactory (S) / Unsatisfactory (U)


S'

Name of Officer: CHANDRA SHEKHAR AZAD

Designation: E.E.



02/07/21
A.E.



02/07/21
(Signature)