

# INSPECTION REPORT FOR FLOOD/RAIN DAMAGE ROAD

Name of Scheme: SH-75 TEKTA RAILWAY GUMTI TO MIRZA MADHUPUR. Hazards: Flood/Rain		
Division: DARBHANSA-2 District: DARBHANSA Actual Length (in km): 1.328 km. Damage Length (in km): 0.465 km. Damages Location/Chainage: 200 to 220 240-260, 350-550 & 800-1025 Metre		
Name of Scheme/Programme: Status of Project: Under Agreement/Out of Agreement		
Sr. No.	Parameters to be Checked in Restoration work	Remarks : (S/U)
1.	Pavement (BT/CC) CC	S
a)	Condition of Surfacing	S
Description of observation : Condition of cc Pavement is good		
b)	Adequate Thickness of pavement layers constructed S	
Description of observation : Adequate thickness found		
c)	Quality of Construction Material Used S	
Description of observation : Good quality of Material used		
d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc. S	
Description of observation : Found in good Condition.		
e)	Compaction of flanks/ slope & raincuts	
Description of observation : Flank work not done work in progress.		
2	Cross Drainage Structure	
a)	Condition of head walls in Hume pipe culverts NA	
b)	Condition of Vent Clearance NA	
C)	Condition of railings/Slab/approach for Bridges NA	
Description of observation of CD works : NA		

Remark if any:

Overall Rating

Satisfactory (S) / Unsatisfactory (U)

S

Name of Officer: CHANDRA SHEKHAR AZAD

Designation: F. E.

02/07/21  
A.P.

02/07/21  
(Signature)