

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD

Name of Scheme: Lo.53 To 2 To Sundarapur Ratawara
 Hazards: Flood/Rain
 Division: Muzaffarpur District: Muzaffarpur Actual Length (in km): 1.069
 Damage Length (in km): 0.110 Damages Location/Chainage: 200.00 - 288.00 M
620.00 - 630.00 M

Name of Scheme/Programme:

Status of Project:

Under Agreement/Out of Agreement

Sr. No.

Parameters to be Checked in Restoration work

Remarks : (S/U)

1.

Pavement (BT/CC)

BT

a)

Condition of Surfacing

S

Description of observation :

Only 30.00m length stretch permanent Restoration work done in out of 110.00m length

b)

Adequate Thickness of pavement layers constructed

S

Description of observation :

c)

Quality of Construction Material Used

S

Description of observation :

d)

Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.

—

Description of observation :

e)

Compaction of flanks/ slope & raincuts

—

Description of observation :

2

Cross Drainage Structure

N.A.

a)

Condition of head walls in Hume pipe culverts

b)

Condition of Vent Clearance

c)

Condition of railings/Slab/approach for Bridges

Description of observation of CD works :

Remark if any:

Only 30.00m length stretch permanent Restoration work done in out of 110.00m length

Overall Rating

Satisfactory (S) / Unsatisfactory (U)

Satisfactory

Name of Officer:

Ram Kumar Mishra

Designation:

EE, R. Lab. Gulsarbag, Patna

02-07-2021

(Signature)