

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD

Name of Scheme: BARID TO KAHARIYA		
Hazards	Flood/Rain	
Division : DARBHANGA-2	District: DARBHANGA	Actual Length (in km): 2.4 Km
Damage Length (in km): 0.410 Km.	Damages Location/Chainage: 100 to 180 & 1100 to 1430 Metre	
Name of Scheme/Programme:		
Status of Project:	Under Agreement/Out of Agreement	
Sr. No.	Parameters to be Checked in Restoration work	Remarks : (S/U)
1.	Pavement (BT/CC)	CC
a)	Condition of Surfacing	'S'
Description of observation : Condition of CC Pavement is good		
b)	Adequate Thickness of pavement layers constructed	'S'
Description of observation : Adequate thickness found		
c)	Quality of Construction Material Used	'S'
Description of observation : Good quality of Material used		
d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.	'S'
Description of observation : Found in good Condition		
e)	Compaction of flanks/ slope & raincuts	
Description of observation : Flank work not done work in Progress.		
2	Cross Drainage Structure	
a)	Condition of head walls in Hume pipe culverts	
b)	Condition of Vent Clearance	
C)	Condition of railings/Slab/approach for Bridges	
Description of observation of CD works : CD work not done		
Remark if any:		

Overall Rating

Satisfactory (S) / Unsatisfactory (U)

'S'Name of Officer: **CHANDRA SHEKHAR AZAD**Designation: **E.E.**

02/07/21
A.E.

02/07/21
(Signature)