

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD

Name of Scheme: L033 to Burhaib Kayasth Tola (Barua)

Hazards: Flood/Rain

Division: Benipur District: Darbhanga

Damage Length (in km): 0.520 Actual Length (in km): 1.025

Name of Scheme/Programme: FDR 350 Damages Location/Chainage: 0 to 520 m

Status of Project: Under Agreement/Out of Agreement

Sr. No.	Parameters to be Checked in Restoration work	Remarks : (S/U)
1.	Pavement (BT/CC)	
a)	Condition of Surfacing	

Description of observation : whole Road submerged in flood. NA

b) Adequate Thickness of pavement layers constructed

Description of observation :

c) Quality of Construction Material Used

Description of observation :

d) Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.

Description of observation :

e) Compaction of flanks/ slope & raincuts

Description of observation :

2 Cross Drainage Structure

a) Condition of head walls in Hume pipe culverts

b) Condition of Vent Clearance

c) Condition of railings/Slab/approach for Bridges

Description of observation of CD works :

Remark if any: The Road submerged in flood so it is not possible to check the Road

Overall Rating

Satisfactory (S) / Unsatisfactory (U) U

Name of Officer: Bindu Rajak
Executive Engineer
 Designation: **RWD, Regional Laboratory**
Darbhanga

03/07/21
A.E.

03/7/21