

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD

Name of Scheme: Gyushenya road to Maluola Juchan

Hazards: Flood/Rain

Division: Dhaka District: East Champaran Actual Length (in km): 5.479 km

Damage Length (in km): 0.2625 km Damages Location/Chainage: —

Name of Scheme/Programme: Restoration

Status of Project: Under Agreement/Out of Agreement

Sr. No	Parameters to be Checked in Restoration work	Remarks (S/U)
--------	--	---------------

1	Pavement (BT/CC)	
---	------------------	--

a)	Condition of Surfacing	—
----	------------------------	---

Description of observation :

Permanent Restoration not work done.

b)	Adequate Thickness of pavement layers constructed	—
----	---	---

Description of observation :

c)	Quality of Construction Material Used	—
----	---------------------------------------	---

Description of observation :

d)	Whether free from any defects and irregularity example: Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc	—
----	--	---

Description of observation :

e)	Compaction of flanks/ slope & raincuts	—
----	--	---

Description of observation :

2	Cross Drainage Structure	
---	--------------------------	--

a)	Condition of head walls in Hume pipe culverts	—
----	---	---

b)	Condition of Vent Clearance	—
----	-----------------------------	---

c)	Condition of railings/Slab/approach for Bridges	—
----	---	---

Description of observation of CD works :

Remark if any:

Permanent Restoration ^{not} work done.

Overall Rating

Satisfactory (S) / Unsatisfactory (U)

U

Sri Kant Prasad.

Name of Officer:

Designation: E.E.

Scanned By Scanner Go

3/3
22/10/24
(Signature)