

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD			
Name of Scheme: Approach Road of H.L. of Chakmaha River at Kothi Bazar Patahi Road			
Hazards		Flood/Rain	
Division: Pakridayal		District: East Champaran	Actual Length (in km): 0.250 km
Damage Length (in km): 0.195 km		Damages Location/Chainage: 0.060 km chorma side	
Name of Scheme/Programme:		FDR (3054)	
Status of Project:		Under Agreement/Out of Agreement	
Sr. No.		Parameters to be Checked in Restoration work	
1.		Pavement (BT/CC) BT	Remarks : (S/U) S
a)		Condition of Surfacing	S
Description of observation :			
MSS surfacing work is in good condition width - 5.0m, 6.0m			
b)		Adequate Thickness of pavement layers constructed	S
Description of observation :			
GSB Gr-II - 200mm WBM Gr-II - 75mm MSS - 20mm			
c)		Quality of Construction Material Used	S
Description of observation :			
Good quality material used			
d)		Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.	N.A.
Description of observation :			
N.A.			
e)		Compaction of flanks/ slope & raincuts	
Description of observation :			
Flank work is in progress			
2		Cross Drainage Structure	
a)		Condition of head walls in Hume pipe culverts	N.A.
b)		Condition of Vent Clearance	S
c)		Condition of railings/Slab/approach for Bridges	S
Description of observation of CD works :			
Bridges found in good condition			
Remark if any:			
Patahi approach road side BT work in progress. Flank work is in progress.			

Overall Rating

Satisfactory (S) / Unsatisfactory (U)	S
---------------------------------------	---

Name of Officer: Ratnesh Paswan

Designation: E.E.

Ratnesh Paswan
2.7.21
E.E.

Ratnesh Paswan
2.7.21
(Signature)

E.E.