

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD

Name of Scheme: LO34 Deepa Tal to Katwasa
 Hazards: Flood/Rain Flood
 Division: Benipur District: Darbhanga Actual Length (in km): 2.01
 Damage Length (in km): 0.800 Damages Location/Chainage: 0 to 1000
 Name of Scheme/Programme: FDR 354 1000 to 2000
 Status of Project: Under Agreement/Out of Agreement ✓

Sr. No.	Parameters to be Checked in Restoration work	Remarks : (S/U)
1.	Pavement (BT/CC) <u>C.C.</u>	
a)	Condition of Surfacing	<u>S</u>

Description of observation : only GSB grading I length - 700m work done

b)	Adequate Thickness of pavement layers constructed	<u>S</u>
----	---	----------

Description of observation : GSB grading I - 100mm

c)	Quality of Construction Material Used	<u>S</u>
----	---------------------------------------	----------

Description of observation :

d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.	<u>N/A</u>
----	---	------------

Description of observation :

e)	Compaction of flanks/ slope & raincuts	
----	--	--

Description of observation : Both side of the Road Built up Area

2	Cross Drainage Structure	
a)	Condition of head walls in Hume pipe culverts	
b)	Condition of Vent Clearance	<u>N/A</u>
c)	Condition of railings/Slab/approach for Bridges	<u>N/A</u>

Description of observation of CD works :

Remark if any: Work in progress

Overall Rating

Satisfactory (S) / Unsatisfactory (U)

Name of Officer: Bindu Rajan
 Designation: Executive Engineer
RWD, Regional Laboratory
Darbhanga

04/07/21
A-E

(Signature)

04/07/21