

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD

Name of Scheme: Narbandh to Supaul
 Hazards: Flood
 Division: Benipur District: Darbhanga Actual Length (in km): 4.99
 Damage Length (in km): 0.878 Damages Location/Chainage:

Name of Scheme/Programme: FDR 3254
 Status of Project: Under Agreement/Out of Agreement

Sr. No.	Parameters to be Checked in Restoration work	Remarks : (S/U)
1.	Pavement (BT/CC)	
a)	Condition of Surfacing	S

Description of observation : On 1705m to 2098 length - 270m
chainage 3905m to 4390m length - 280m
520m

b)	Adequate Thickness of pavement layers constructed	S
----	---	---

Description of observation : P.C.C. - 160mm

c)	Quality of Construction Material Used	S
----	---------------------------------------	---

Description of observation :

d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.	S
----	---	---

Description of observation :

e)	Compaction of flanks/ slope & raincuts	
----	--	--

Description of observation : Both side of Road built up Area

2	Cross Drainage Structure	
a)	Condition of head walls in Hume pipe culverts	N.A
b)	Condition of Vent Clearance	N.A
c)	Condition of railings/Slab/approach for Bridges	N.A

Description of observation of CD works :

Remark if any: P.C.C. length 358m work in progress

Overall Rating:

Satisfactory (S) / Unsatisfactory (U)

Satisfactory

Name of Officer:

Binod Kumar
Executive Engineer

Designation:

RWD, Regional Laboratory
Darbhanga

(Signature)

04/07/21