

INSPECTION REPORT FOR FLOOD/RAIN DAMAGE ROAD		
Name of Scheme <u>Chiraiya to Ananahiya Part-II</u>		
Hazards <u>Flood/Rain</u>		
Division <u>Dhaka</u>	District <u>East Champaran</u>	Actual Length (in km) <u>7.600 km</u>
Damage Length (in km) <u>0.818 km</u>	Damages Location/Chainage: <u>—</u>	
Name of Scheme/Programme: <u>Restoration</u>		
Status of Project <u>Under Agreement/Out of Agreement</u>		
Sr. No	Parameters to be Checked in Restoration work	Remarks (S/U)
1	Pavement (BI/CC)	
a)	Condition of Surfacing	<u>—</u>
Description of observation :		
b)	Adequate Thickness of pavement layers constructed	<u>—</u>
Description of observation :		
c)	Quality of Construction Material Used	<u>—</u>
Description of observation :		
d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.	<u>—</u>
Description of observation :		
e)	Compaction of flanks/ slope & raincuts	<u>—</u>
Description of observation :		
2	Cross Drainage Structure	
a)	Condition of head walls in Hume pipe culverts	<u>—</u>
b)	Condition of Vent Clearance	<u>—</u>
c)	Condition of railings/Slab/approach for Bridges	<u>—</u>
Description of observation of CD works :		
Remark if any:		
<u>Permanent Restoration work not done.</u>		
Overall Rating		

Sri Kant Prasad
Name of Officer

Designation E.E.

Satisfactory (S) / Unsatisfactory (U)

U

23/07/21

SHU021
(Signature)