

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD

Name of Scheme: MADHOPUR TO BANALI VIA FULTHUA.		
Hazards	Flood/Rain	
Division : DARBHANGA-2	District: DARBHANGA	Actual Length (in km): 7.0 km.
Damage Length (in km): 0.790 km	Damages Location/Chainage: 100-310 ; 320-550 & 1300 - 1650 Meter	
Name of Scheme/Programme:		
Status of Project:	Under Agreement/Out of Agreement	
Sr. No.	Parameters to be Checked in Restoration work	Remarks : (S/U)
1.	Pavement (BT/CC) CC	
a)	Condition of Surfacing	S
Description of observation : Condition of cc Pavement is good		
b)	Adequate Thickness of pavement layers constructed	S
Description of observation : Adequate thickness found		
c)	Quality of Construction Material Used	S
Description of observation : Good quality of Material used		
d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement , Poor workmanship, etc.	S
Description of observation : Found in good Condition		
e)	Compaction of flanks/ slope & raincuts	
Description of observation : Not done , in progress		
2	Cross Drainage Structure	
a)	Condition of head walls in Hume pipe culverts	NA
b)	Condition of Vent Clearance	NA
C)	Condition of railings/Slab/approach for Bridges	NA
Description of observation of CD works : NA		
Remark if any:		
Overall Rating		

Satisfactory (S) / Unsatisfactory (U)

S

Name of Officer: CHANDRA SHEKHAR AZAD

Designation: E.E.

03/07/21
A.E.

0317121
(Signature)