

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD

Name of Scheme: <u>TOI TO FULTHUA</u>		
Hazards	Flood/Rain	
Division : <u>DARBHANGA-2</u>	District: <u>DARBHANGA</u>	Actual Length (in km): <u>2.950 Km.</u>
Damage Length (in km): <u>0.675 km</u>	Damages Location/Chainage: <u>0 to 675 Metre</u>	
Name of Scheme/Programme:		
Status of Project:	Under Agreement/Out of Agreement	
Sr. No.	Parameters to be Checked in Restoration work	Remarks : (S/U)
1.	Pavement (BT/CC) <u>CC</u>	<u>'S'</u>
a)	Condition of Surfacing	
Description of observation : <u>Condition of CC Pavement is good</u>		
b)	Adequate Thickness of pavement layers constructed	<u>'S'</u>
Description of observation : <u>Adequate thickness found</u>		
c)	Quality of Construction Material Used	<u>'S'</u>
Description of observation : <u>Good quality of Material used</u>		
d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.	<u>'S'</u>
Description of observation : <u>Found in good Condition</u>		
e)	Compaction of flanks/ slope & raincuts	
Description of observation : <u>Flank work in Progress</u>		
2	Cross Drainage Structure	
a)	Condition of head walls in Hume pipe culverts	<u>NA</u>
b)	Condition of Vent Clearance	<u>NA</u>
c)	Condition of railings/Slab/approach for Bridges	<u>NA</u>
Description of observation of CD works : <u>NA</u>		
Remark if any:		

Overall Rating

Satisfactory (S) / Unsatisfactory (U)

'S'Name of Officer: CHANDRA SHERHAR AZADDesignation: E.E.

03/07/21
A-E

03/07/21
(Signature)