

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD		
Name of Scheme: <u>Ushamath to kamalpur via kokal</u>		
Hazards	Flood/Rain	
Division : <u>Darbhanga-1</u>	District: <u>Darbhanga</u>	Actual Length (in km): <u>2.950 km</u>
Damage Length (in km): <u>0.985 km</u>	Damages Location/Chainage: <u>—</u>	
Name of Scheme/Programme:	<u>FDR</u>	
Status of Project:	Under Agreement/Out of Agreement <u>Out of Agreement</u>	
Sr. No.	Parameters to be Checked in Restoration work	Remarks : (S/U)
1.	Pavement (BT/CC)	
a)	Condition of Surfacing	<u>S</u>
Description of observation : <u>MSS - 20 MM BT done in length 0.750 km</u> <u>CC pavement - 160 MM done in length 0.235 km</u>		
b)	Adequate Thickness of pavement layers constructed	<u>S</u>
Description of observation : <u>100 MM - GSB Gr I in patches & cc portion</u> <u>75 MM - Gr II in patches & cc portion</u>		
c)	Quality of Construction Material Used	<u>S</u>
Description of observation : <u>Good quality</u>		
d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.	<u>S</u>
Description of observation : <u>—</u>		
e)	Compaction of flanks/ slope & raincuts	<u>S</u>
Description of observation : <u>Flank E/W in cement concrete Pavement is to be done. In B.T. part flank E/W in progress.</u>		
2	Cross Drainage Structure	
a)	Condition of head walls in Hume pipe culverts	<u>—</u>
b)	Condition of Vent Clearance	<u>—</u>
C)	Condition of railings/Slab/approach for Bridges	<u>—</u>
Description of observation of CD works : <u>No provision in the scheme.</u>		
Remark if any: <u>Restoration work done.</u>		

Overall Rating

Satisfactory (S) / Unsatisfactory (U)	<u>S</u>
---------------------------------------	----------

Name of Officer:

Ram Prabesh Saw

Designation:

T.A, RWA
Work circle, Siwan

(Signature)

4.7.21

4/7/21
AE