

INSPECTION REPORT FOR FLOOD/RAIN DAMAGE ROAD

Name of Scheme:	PMGSY Road to Mahalbari	
Hazards	Flood Rain	
Division: Krishnagar	District: Krishnagar	Actual Length (in km): 1.313
Damage Length (in km): 0.040	Damages Location/Chaining: 0.500	
Name of Scheme/Programme:	FDR	
Status of Project:	Under Agreement/Out of Agreement	
Sl. No.	Parameters to be Checked in Restoration work	Remarks : (S/U)
a)	Pavement (BT/CC) BT	S
	Condition of Surfacing	
Description of observation : Good.		
b)	Adequate Thickness of pavement layers constructed	S
Description of observation : M.S.S. 20mm thickness		
c)	Quality of Construction Material Used	S
Description of observation : Satisfactory.		
d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.	S
Description of observation : No undulations		
e)	Compaction of flanks/ slope & railcuts	S
Description of observation : A few minor found. Need to be repaired		
2	Cross Drainage Structure	
a)	Condition of head walls in Hume pipe culverts	
b)	Condition of Vent Clearance	
c)	Condition of railings/Stab/approach for Bridges	
Description of observation of CD works : No provision		
Remark if any:		
Overall Rating	Satisfactory (S) / Unsatisfactory (U) Satisfactory	

Name of Officer: Mahesh P. Gupta
 Designation: EC, RWD, Regional Lab.
 Purba

04/07/2014
 (Signature)