

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD

Name of Scheme: L054 To2 To Gannipur Begha		
Hazards	Flood/Rain	
Division : Muzaffarpur-1	District: Muzaffarpur	Actual Length (in km): 2.496
Damage Length (in km): 0.650	Damages Location/Chainage: 1.770 KM - 2.020 KM, 2.040 KM - 2.090 KM 2.110 KM - 2.208 KM, 2.230 KM - 2.398 KM 2.400 KM - 2.484 KM	
Name of Scheme/Programme:		
Status of Project:	Under Agreement/Out of Agreement	
Sr. No.	Parameters to be Checked in Restoration work	Remarks : (S/U)
1.	Pavement (BT/CC)	—
a)	Condition of Surfacing	U
Description of observation : Permanent Restoration work not started in damages location.		
b)	Adequate Thickness of pavement layers constructed	—
Description of observation :		
c)	Quality of Construction Material Used	—
Description of observation :		
d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.	—
Description of observation :		
e)	Compaction of flanks/ slope & raincuts	—
Description of observation :		
2	Cross Drainage Structure	N.A.
a)	Condition of head walls in Hume pipe culverts	—
b)	Condition of Vent Clearance	—
c)	Condition of railings/Slab/approach for Bridges	—
Description of observation of CD works :		
Remark if any: Permanent Restoration work not started in damages location.		

Overall Rating

Satisfactory (S) / Unsatisfactory (U)	Unsatisfactory
---------------------------------------	----------------

Name of Officer: Ram Kumar Mishra

Designation: E.E. R. Lab Gulzarbag, Patna

03/07/2024 (Signature)