

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD

Name of Scheme: Bahara Pokhar to Khairwa		
Hazards: Flood/Rain		
Division: Pakoidaya	District: East Champaran	Actual Length (in km): 5.00 km
Damage Length (in km): 0.220 km	Damages Location/Chainage: 0.450 km, 0.850 km	
Name of Scheme/Programme: FDR (3054)		
Status of Project: Under Agreement/Out of Agreement		
Sr. No.	Parameters to be Checked in Restoration work	Remarks : (S/U)
1.	Pavement (BT/CC) BT	S
a)	Condition of Surfacing	S
Description of observation : MSS surfacing work is in good condition BT work done in 102 m length. Remaining part BT work is in progress.		
b)	Adequate Thickness of pavement layers constructed	S
Description of observation : GSB Gr-II - 100 mm WBM Gr III - 75 mm MSS - 20 mm		
c)	Quality of Construction Material Used	S
Description of observation : Good quality material used		
d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.	N.A.
Description of observation : N.A.		
e)	Compaction of flanks/ slope & raincuts	
Description of observation : Flank work in progress		
2	Cross Drainage Structure	
a)	Condition of head walls in Hume pipe culverts	N.A.
b)	Condition of Vent Clearance	S
c)	Condition of railings/Slab/approach for Bridges	N.A.
Description of observation of CD works : Rcc culvert found in good condition -		
Remark if any: BT work done in 102 m length. Remaining part BT work is in progress.		

Overall Rating

Satisfactory (S) / Unsatisfactory (U)	S
---------------------------------------	----------

Name of Officer: **Ratnesh Paswan**

Designation: **E.E.**

[Signature]
4/7/21
A.E.

[Signature]
(Signature)
E.E.