

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD			
Name of Scheme: Tetaria to Maniyarpur			
Hazards		Flood/Rain	
Division: Pakhridyal		District: East Champaran	Actual Length (in km): 4.00 km
Damage Length (in km): 0.282 km		Damages Location/Chainage: 1.800 km, 1.905 km	
Name of Scheme/Programme:		FDR (3054)	
Status of Project:		Under Agreement/Out of Agreement	
Sr. No.	Parameters to be Checked in Restoration work		Remarks : (S/U)
1.	Pavement (BT/CC) BT		S
a)	Condition of Surfacing		S
Description of observation :			
MSS Surfacing work is in good condition. BT work done is 45 m length.			
b)	Adequate Thickness of pavement layers constructed		S
Description of observation :			
GSB Gr-II - 100 mm WBM Gr-III - 75 mm MSS - 20 mm			
c)	Quality of Construction Material Used		U
Description of observation :			
WBM Gr-III material is not properly compacted in 90m.			
d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.		N.A.
Description of observation :			
N.A.			
e)	Compaction of flanks/ slope & raincuts		
Description of observation :			
Flank work in progress.			
2	Cross Drainage Structure		
a)	Condition of head walls in Hume pipe culverts		S
b)	Condition of Vent Clearance		S
c)	Condition of railings/Slab/approach for Bridges		N.A.
Description of observation of CD works :			
CD work found in good condition.			
Remark if any:			
WBM Gr-III material is not properly compacted in 90m.			
Overall Rating			
Satisfactory (S) / Unsatisfactory (U)			U

Name of Officer: Ratnesh Paswan

Designation: E.E.

B Kumar
4/7/21
A.E.

Signature
4-7-21
E.E.