

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD			
Name of Scheme: <u>Kaushalya Kazarah Nona to Madhuban Sheohar Sima</u>			
Hazards		Flood/Rain	
Division: <u>Pakaridaya</u>		District: <u>East Champaran</u>	Actual Length (in km): <u>0.850 km</u>
Damage Length (in km): <u>0.100 km</u>		Damages Location/Chainage: <u>0.450 km</u>	
Name of Scheme/Programme:		<u>FDR (3054)</u>	
Status of Project:		Under Agreement/Out of Agreement	
Sr. No.	Parameters to be Checked in Restoration work		Remarks : (S/U)
1.	Pavement (BT/CC) <u>BT</u>		<u>S</u>
a)	Condition of Surfacing		<u>S</u>
Description of observation : <u>MSS surfacing work is in good condition.</u>			
<u>BT work done in 54m length. Remaining part work is in progress.</u>			
b)	Adequate Thickness of pavement layers constructed		<u>S</u>
Description of observation : <u>GSB Gr-II - 100mm</u>			
<u>WBM Gr-III - 75mm</u>			
<u>MSS - 20mm</u>			
c)	Quality of Construction Material Used		<u>S</u>
Description of observation : <u>Good quality material is used</u>			
d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.		<u>N.A.</u>
Description of observation : <u>N.A.</u>			
e)	Compaction of flanks/ slope & raincuts		
Description of observation : <u>Flank work in progress</u>			
2	Cross Drainage Structure		
a)	Condition of head walls in Hume pipe culverts		<u>N.A.</u>
b)	Condition of Vent Clearance		<u>N.A.</u>
c)	Condition of railings/Slab/approach for Bridges		<u>N.A.</u>
Description of observation of CD works : <u>N.A.</u>			
Remark if any: <u>BT work done in 54m length. Remaining part BT work is in progress.</u>			

Overall Rating

Satisfactory (S) / Unsatisfactory (U)	<u>S</u>
---------------------------------------	----------

Name of Officer: Ratnesh Paswan

Designation: E.E.

B. Kumar
4/7/21
A.E.

4-7-21
(Signature)
E.E.