

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD		
Name of Scheme: <u>T01 TO BIRDIPUR</u>		
Hazards	Flood/Rain	
Division: <u>DARBHANGA-2</u>	District: <u>DARBHANGA</u>	Actual Length (in km): <u>1.950 KM</u>
Damage Length (in km): <u>0.580 KM</u>	Damages Location/Chainage: <u>0 to 430 M.</u>	
Name of Scheme/Programme:		
Status of Project:	Under Agreement/Out of Agreement	
Sr. No.	Parameters to be Checked in Restoration work	Remarks : (S/U)
1.	Pavement (BT/CC) <u>CC</u>	
a)	Condition of Surfacing	<u>S</u>
Description of observation : <u>Condition of Surfacing is good out of 580M length 430M length has been done,</u>		
b)	Adequate Thickness of pavement layers constructed	<u>S</u>
Description of observation : <u>Adequate thickness found</u>		
c)	Quality of Construction Material Used	<u>S</u>
Description of observation : <u>Good quality of Material found</u>		
d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.	<u>S</u>
Description of observation : <u>Found in good Condition.</u>		
e)	Compaction of flanks/ slope & raincuts	
Description of observation : <u>work in progress.</u>		
2	Cross Drainage Structure	
a)	Condition of head walls in Hume pipe culverts	<u>NA</u>
b)	Condition of Vent Clearance	<u>NA</u>
c)	Condition of railings/Slab/approach for Bridges	<u>NA</u>
Description of observation of CD works : <u>NA</u>		
Remark if any:		

Overall Rating

Satisfactory (S) / Unsatisfactory (U)

'S'

Name of Officer: CHANDRA SHEKHAR A2ADDesignation: E.E.

03/07/21
A.E.

0317121
(Signature)