

INSPECTION REPORT FOR FLOOD/RAIN DAMAGE ROAD

Name of Scheme: Hayaghat BHO to Aliyabad Path

Hazards: Flood/Rain

Division: Darbhanga-1 District: Darbhanga Actual Length (in km): 2.50 km

Damage Length (in km): 2.50 km Damages Location/Chainage:

Name of Scheme/Programme: FDR

Status of Project: Under Agreement/Out of Agreement Out of Agreement

Sr. No. Parameters to be Checked in Restoration Work Remarks: (S/U)

1. Pavement (BT/CC)

a) Condition of Surfacing S

Description of observation:

In 200 metre BT done. In 2.3 km BT work is to be done.

b) Adequate Thickness of pavement layers constructed S

Description of observation:

100mm G.S.B-G.O.I & 75mm WBM G.O.I in patches done.

c) Quality of Construction Material Used S

Description of observation:

Good quality.

d) Whether free from any defects and Irregularity example-Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc. S

Description of observation:

e) Compaction of flanks/ slope & raincuts -

Description of observation:

No provision in this scheme.

2 Cross Drainage Structure

a) Condition of head walls in Hume pipe culverts -

b) Condition of Vent Clearance -

c) Condition of railings/Slab/approach for Bridges -

Description of observation of CD works:

No provision in the scheme.

Remark if any: Restoration work completed with WBM G.O.I. BT work to be done in about 2.30 km.

Overall Rating

Satisfactory (S) / Unsatisfactory (U)

S

Name of Officer: Ram Prabesh Saw

Designation: T.A., RWD
Work circle Sivan

3/7/21
AE
(Signature)