

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD

Name of Scheme: CPWD Road Mayaghat to Rajauli

Hazards Flood/Rain

Division: Darbhanga-1 District: Darbhanga Actual Length (in km): 1.50 km

Damage Length (in km): 0.6094 Damages Location/Chainage:

Name of Scheme/Programme: PDR

Status of Project: Under Agreement/Out of Agreement Out of Agreement

Sr. No. Parameters to be Checked in Restoration work Remarks : (S/U)

1. Pavement (BT/CC)

a) Condition of Surfacing S

Description of observation :

P.C.C in about 120 Metre length done. Work in progress.

b) Adequate Thickness of pavement layers constructed S

Description of observation :

CC - Thickness - 160 mm

c) Quality of Construction Material Used

Description of observation :

Good quality of material used.

d) Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc. S

Description of observation :

e) Compaction of flanks/ slope & raincuts

Description of observation :

No provision in this scheme.

2 Cross Drainage Structure

a) Condition of head walls in Hume pipe culverts

b) Condition of Vent Clearance

c) Condition of railings/Slab/approach for Bridges

Description of observation of CD works :

No provision in this scheme.

Remark if any: Restoration done. P.C.C work in progress

Overall Rating

Satisfactory (S) / Unsatisfactory (U)

S

Name of Officer:

San Babesh San

Designation:

TA, RWD
Work Circle Siwan

(Signature)

3/7/21
AE