

**INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD**

Name of Scheme: L058 PMGSY MD. DANI TO BAJIDPUR		
Hazards	Flood/Rain	
Division : DARBHANGA-2	District: DARBHANGA	Actual Length (in km): 5.196 KM
Damage Length (in km): 0.150 km. with	Damages Location/Chainage:	
Name of Scheme/Programme:	Protection Wall (300M.) & RCC Culvert (1X3X2.0 M.)	
Status of Project:	Under Agreement/Out of Agreement	
Sr. No.	Parameters to be Checked in Restoration work	Remarks : (S/U)
1.	Pavement (BT/CC) CC	
a)	Condition of Surfacing	
Description of observation :		
CC work not started yet		
b)	Adequate Thickness of pavement layers constructed	
Description of observation :		
CC work not started yet		
c)	Quality of Construction Material Used	S
Description of observation :		
Good		
d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.	
Description of observation :		
CC work not started yet		
e)	Compaction of flanks/ slope & raincuts	
Description of observation :		
Not started		
2	Cross Drainage Structure	
a)	Condition of head walls in Hume pipe culverts	
b)	Condition of Vent Clearance	
c)	Condition of railings/Slab/approach for Bridges	
Description of observation of CD works :		
Protection wall found in good condition, CD work not started yet.		
Remark if any:		


Overall Rating


Satisfactory (S) / Unsatisfactory (U)

S

Name of Officer: CHANDRA SHEKHAR AZAD

Designation: F.E.


  
04/07/21


  
0417121  
(Signature)