

(9)

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD

Name of Scheme: <u>PWD TO BITHAULT</u>		
Hazards	Flood/Rain	
Division: <u>DARBHANGA-2</u>	District: <u>DARBHANGA</u>	Actual Length (in km): <u>1.130 Km.</u>
Damage Length (in km): <u>0.210 Km.</u>	Damages Location/Chainage: <u>P/wall- 200-235, 850 to 895 Meter</u>	
Name of Scheme/Programme:		
Status of Project:	Under Agreement/Out of Agreement	
Sr. No.	Parameters to be checked in Restoration work	Remarks : (S/U)
1.	Pavement (BT/CC) <u>CC</u>	
a)	Condition of Surfacing	
Description of observation : <u>cc Pavement work not started</u>		
b)	Adequate Thickness of pavement layers constructed	
Description of observation : <u>Not started</u>		
c)	Quality of Construction Material Used	<u>'S'</u>
Description of observation : <u>Good</u>		
d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.	
Description of observation : <u>work of cc Pavement not started</u>		
e)	Compaction of flanks/ slope & raincuts	
Description of observation : <u>Not started</u>		
2	Cross Drainage Structure	
a)	Condition of head walls in Hume pipe culverts	
b)	Condition of Vent Clearance	
C)	Condition of railings/Slab/approach for Bridges	
Description of observation of CD works : <u>80 M Protection wall Completed.</u> <u>1 No. Culvert work not started.</u>		
Remark if any:		

Overall Rating

Satisfactory (S) / Unsatisfactory (U)

'S'

Name of Officer: CHANDRA SHEKHAR AZADDesignation: E.E.

02/07/21
A.E.

8217121
(Signature)