

**INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD**

Name of Scheme: <u>RED ROAD TO CHANDI</u>		
Hazards	Flood/Rain	
Division : <u>DARBHANGA-2</u>	District: <u>DARBHANGA</u>	Actual Length (in km): <u>2.10 Km</u>
Damage Length (in km): <u>0.050km</u>	Damages Location/Chainage:	
Name of Scheme/Programme: <u>With Protection wall (150 Meters) &amp; Two RCC Culvert (1x5x2.5 M)</u>		
Status of Project:	Under Agreement/Out of Agreement	
Sr. No.	Parameters to be Checked in Restoration work	Remarks : (S/U)
1.	Pavement (BT/CC)	
a)	Condition of Surfacing	
Description of observation :		
<u>NA</u>		
b)	Adequate Thickness of pavement layers constructed	
Description of observation :		
<u>NA</u>		
c)	Quality of Construction Material Used	
Description of observation :		
d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement , Poor workmanship, etc.	
Description of observation :		
<u>Work not yet started</u>		
e)	Compaction of flanks/ slope & raincuts	
Description of observation :		
2	Cross Drainage Structure	
a)	Condition of head walls in Hume pipe culverts	
b)	Condition of Vent Clearance	
c)	Condition of railings/Slab/approach for Bridges	
Description of observation of CD works :		
<u>CD work and Protection wall Construction not yet started.</u>		
Remark if any:		

Overall Rating

Satisfactory (S) / Unsatisfactory (U)

'U'Name of Officer: CHANDRA SHEKHAR AZADDesignation: E.E.

04/07/24  
A.E.

04/07/24  
(Signature)