

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD		
Name of Scheme:	Dholbag Middle school to Path Nirman	
Hazards	Flood/Rain	
Division:	Madhubani	District: Madhubani Actual Length (in km): 1.500
Damage Length (in km):	0.250	Damages Location/Chainage:
Name of Scheme/Programme:	PMUSY	
Status of Project:	Under Agreement/Out of Agreement	
Sr. No.	Parameter's to be Checked in Restoration work	Remarks : (S/U)
1.	Pavement (BT/CC)	S
a)	Condition of Surfacing	S
Description of observation :		

b)	Adequate Thickness of pavement layers constructed	S
Description of observation :		
c)	Quality of Construction Material Used	S
Description of observation :		
d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.	—
Description of observation :		

e)	Compaction of flanks/slope & rain
Description of observation: ELW not done in 2 flanks.	
2	Cross Drainage Structure
a)	Condition of head walls in Hume pipe culverts
b)	Condition of Vent Clearance
c)	Condition of railings/Slab/approach for Bridges
Description of observation of CD works :	
Remark if any: Carriage width and works in it found satisfactory. ELW not started in road flanks.	

Overall Rating

Satisfactory (S) / Unsatisfactory (U)

S

Name of Officer: KUMAR RAKESH

Designation: तकनीकी सलाहकार
ग्रामीण कार्य विभाग
कार्य अंचल, पटना

27/7/21
HC

Signature: 02/07/21