

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD

Name of Scheme: Tarapati Mettled Road to Palimohan Mettled Rd.

Hazards: Flood/Rain

Division: Madhubani District: Madhubani Actual Length (in km): 4.800

Damage Length (in km): 0.540 Damages Location/Chainage: Photo attached

Name of Scheme/Programme: old MMUSY

Status of Project: Under Agreement/Out of Agreement

Sr. No.	Parameters to be Checked in Restoration work	Remarks : (S/U)
1.	Pavement (BT/CC)	U
a)	Condition of Surfacing	U

Description of observation: Laying and Rolling temp. not maintained.

b)	Adequate Thickness of pavement layers constructed	S
----	---	---

Description of observation:

c)	Quality of Construction Material Used	U
----	---------------------------------------	---

Description of observation: Gr-III material not in proper grade. Dusty material seen.

d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.	
----	---	--

Description of observation:

e)	Compaction of flanks/slope & ramp	S
----	-----------------------------------	---

Description of observation:

2	Cross Drainage Structure	
a)	Condition of head walls in Hume pipe culverts	
b)	Condition of Vent Clearance	N/A
c)	Condition of railings/Slab/approach for Bridges	

Description of observation of CD works:

Remark if any: Laying and rolling temp. of mss not maintained. Gr. III poor.

Overall Rating

Satisfactory (S) / Unsatisfactory (U)

Name of Officer: KUMAR RAKESH

Designation: तकनीकी सलाहकार
ग्रामीण कार्य विभाग
कार्य अंचल, पटना

31/7/21
HE

(Signature)

03.07.21