

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD

Name of Scheme:	Kamlaavasi to Udaypur Bithur		
Hazards	Flood/Rain		
Division:	Madhubani	District:	Madhubani
Damage Length (in km):	0.626	Actual Length (in km):	3.56
Name of Scheme/Programme:	MMUSP		
Status of Project:	Under Agreement/Out of Agreement		
Damages Location/Chainage:	Photo Attached		
Sr. No.	Parameters to be Checked in Restoration work	Remarks : (S/U)	
1.	Pavement (BT/CC)	U	
a)	Condition of Surfacing	U	

Description of observation : In village portion mss found damaged due to water accumulation.

b)	Adequate Thickness of pavement layers constructed	S
Description of observation :		
c)	Quality of Construction Material Used	S
Description of observation :		
d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.	-

Description of observation :

e)	Compaction of flanks/ slope & rain	U
Description of observation :		
2	Cross Drainage Structure	-
a)	Condition of head walls in Hume pipe culverts	-
b)	Condition of Vent Clearance	-
c)	Condition of railings/Slab/approach for Bridges	-

Description of observation of CD works : An

Remark if any: mss damaged in village portion due to rain water accumulation.

Overall Rating

Satisfactory (S) / Unsatisfactory (U)

U

Name of Officer: KUMAR RAKESH

Designation: तकनीकी सलाहकार
ग्रामीण कार्य विभाग
कार्य अंचल, पटना

11/7/21
HE

(Signature)

01.07.21