

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD		
Name of Scheme: <u>Chandradih to Marukia</u>		
Hazards: <u>Flood/Rain</u>		
Division: <u>Madhubani</u>	District: <u>Madhubani</u>	Actual Length (in km): <u>13.31</u>
Damage Length (in km): <u>1.225</u>	Damages Location/Chainage: <u>Photo attached</u>	
Name of Scheme/Programme: <u>PMUSY</u>		
Status of Project: <u>Under Agreement/Out of Agreement</u>		
Sr. No.	Parameters to be Checked in Restoration work	Remarks : (S/U)
1.	Pavement (BT/CC)	<u>U</u>
a)	Condition of Surfacing	<u>U</u>
Description of observation: <u>Laying & Rolling temp. of Mss not maintained. Disintegration seen in some stretches</u>		
b)	Adequate Thickness of pavement layers constructed	<u>S</u>
Description of observation:		
c)	Quality of Construction Material Used	<u>S</u>
Description of observation:		
d)	Whether free from any defects and irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.	<u>-</u>
Description of observation:		
e)	Compaction of flanks/ slope & run.	<u>U</u>
Description of observation: <u>EW not done in flanks.</u>		
2	Cross Drainage Structure	
a)	Condition of head walls in Hume pipe culverts	
b)	Condition of Vent Clearance	<u>N/A</u>
c)	Condition of railings/Slab/approach for Bridges	
Description of observation of CD works:		
Remark if any: <u>Laying and Rolling temp. of mss not maintained.</u>		

Overall Rating

Satisfactory (S) / Unsatisfactory (U)

Name of Officer: KUMAR RAKESH

Designation: तकनीकी सलाहकार
ग्रामीण कार्य विभाग
कार्य अंचल, पटना

(Signature)

Recd
21/7/21
42

02.07.21