

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD		
Name of Scheme: <u>Toz to Kakasghati</u>		
Hazards: <u>Flood/Rain</u>		
Division: <u>Madhubani</u>	District: <u>Madhubani</u>	Actual Length (in km): <u>4.479</u>
Damage Length (in km): <u>0.300</u>		Damages Location/Chainage:
Name of Scheme/Programme: <u>PMUSY</u>		
Status of Project: <u>Under Agreement/Out of Agreement</u>		
Sr. No.	Parameters to be Checked in Restoration work	Remarks : (S/U)
1.	Pavement (BT/CC)	<u>U</u>
a)	Condition of Surfacing	<u>U</u>
Description of observation : <u>Laying and rolling temp. of MSS not maintained. Disintegration found.</u>		
b)	Adequate Thickness of pavement layers constructed	<u>S</u>
Description of observation :		
c)	Quality of Construction Material Used	<u>S</u>
Description of observation :		
d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.	<u>N/A</u>
Description of observation :		
e) <u>Compaction of flanks/ slope & rain.</u>		
Description of observation: <u>FW in flank not done in the flank.</u>		
2	Cross Drainage Structure	
a)	Condition of head walls in Hume pipe culverts	<u>N/A</u>
b)	Condition of Vent Clearance	
c)	Condition of railings/Slab/approach for Bridges	
Description of observation of CD works :		
Remark if any: <u>Laying and rolling temp. not maintained. Disintegration found.</u>		

Overall Rating

Satisfactory (S) / Unsatisfactory (U)

U

Name of Officer: KUMAR RAKESH

Designation: तकनीकी सलाहकार
ग्रामीण कार्य विभाग
कार्य अंचल, पटना

(Signature)

03.07.21

31/7/21
42